Region 7 Superfund Program Addendum to the QAPP for the Superfund Site Assessment and Targeted Brownfields Assessment Programs (October 2012)	
for the Atlantic Groundwater Site	
Project Information:	Citato Administra
Project Name: Atlantic Groundwater Site EPA Project Manager: \$usan Fister	City: Atlantic State: IA START Project Manager: David Zimmermann
Approved By: Would Jonath	START Project Manager. David Zammermann
Title: START Project Manager Date: 8-22-14	P CDA Police 7 Secretaria Division
Approved By:	Prepared For: EPA Region 7 Superfund Division
Title: START Program Manager Date: 8-22-14	
Approved By:	Prepared By: David Zimmermann
For Title: START QA Manager Date: 8 -22-14	Date: August 2014
Approved By: Susan Fish	
Approved By: Date 8 - 26 14	Tetra Tech START Project Number:
Approved By: Dame Tarria Title: EPA Region 7 QA Manager Date: 09/10/2014	X9025.14.0030.000
1.0 Project Management:	
1.1 Distribution List	
	START: David Zimmermann, Project Manager Kathy Homer, QA Manager
1.2 Project/Task Organization	
Susan Fisher, of the EPA Region 7 Superfund Division, will serve as the EPA Project Manager for the activities described in this QAPP. David Zimmermann, of Tetra Tech, Inc., will serve as the START Project Manager for field activities. 1.3 Problem Definition/Background:	
Description: This site-specific Quality Assurance Project Plan form is prepared as an addendum to the Generic Quality Assurance Project Plan for the Superfund Site Assessment and Targeted Brownfields Assessment Programs (updated October 2012), and contains site-specific data quality objectives for the sampling activities described herein.	
Description attached.	
Description in referenced report:	Date
Title	Date
1.4 Project/Task Description: □ CERCLA PA □ CERCLA SI □ Brownfields Assessment □ Removal Action □ Other (description attached): □ Pre-CERCLIS Area Screening □ Removal Site Evaluation Other Description: Schedule: Field activities are scheduled to begin in September 2014 and are anticipated to take 5 days to complete.	
Description in referenced report:	
Title	Date
1.5 Quality Objectives and Criteria for Measurement Data:	
Accuracy:	✓ Identified in attached table.
Precision:	☐ Identified in attached table.
Representativeness:	☐ Identified in attached table.
Completeness*:	☐ Identified in attached table. ☐ Identified in attached table.
Comparability:	☐ Identified in attached table.
Other Description: *A completeness goal of 100 percent has been established for this project. However, if the completeness goal is not met, EPA may still be able to make decisions based on any or all of the remaining validated data.	
1.6 Special Training/Certification Requirements:	
□ OSHA 1910 □ Special Equipment/Instrument Operator (describe below): □ Other (describe below): Iowa Certified Well Contractor will be required of the subcontracted monitoring well installer. 1.7 Documentation and Records:	
☒ Field Sheets ☒ Daily Log ☐ Trip Report ☒ Chain of Custody ☒ Health and Safety Plan ☒ Letter Report	☑ Area Maps☑ Video☑ Photos
Sample documentation will follow EPA Region 7 SOP 2420.05.	
Other: Analytical information will be handled according to procedures identified in Table	RECEIVE

A7-2Q 40477231 1.0
Superfund